



## PLASMA CUTTING MACHINE

Model	Width(mm) A	Lenght (mm) B	Height(mm) C	Cutting Width (mm) D	Cutting Length (mm) D	Weight(KG)
APL 15/30	2650	4400	2150	1650	1650	3650
APL 20/40	3150	5400	2150	2150	2150	4800
APL 20/60	3150	7400	2150	2150	2150	5950
APL 30/60	4150	7400	2150	3150	3150	7400
APL 30/80	4150	9400	2150	3150	3150	3200
APL30/120	4150	13400	2150	3150	3150	12600
APL30/160	4150	17400	2150	3150	3150	16100
APL20/200	4150	21400	2150	3150	3150	19500
APL40/60	5150	7400	2150	4150	4150	8900
APL40/80	5150	9400	2150	4150	4150	11100
APL40/120	5150	13400	2150	4150	4150	15400
APL40/160	5150	17400	2150	4150	4150	19700
APL40/200	5150	21400	2150	4150	4150	24000



HSD 130	Mild Steel		Stainless / Aluminum	
	Pierce	Edge Start	Pierce	Edge Start
HSD 130	25 mm.	38 mm.	20 mm.	25 mm.
HPR 130 XD	25 mm.	38 mm.	20 mm.	25 mm.
HPR 260 XD	38 mm.	63 mm.	32 mm.	50 mm.
HPR 400 XD	50 mm.	80 mm.	45 mm.	80 mm.
HPR 800 XD	50 mm.	80 mm.	80 mm.	160 mm.